



Certification

C E R T I F I C A T E

awarded to

PATENTES TALGO S.L.U.
PASEO DEL TREN TALGO Nº 2
28290, LAS MATAS
Spain

AENOR INTERNACIONAL, S.A.U.

confirms, as an IRIS Certification® approved certification body, that the Management System of the above organization has been assessed and found to be in accordance with the

IRIS Certification® Conformity assessment:2020 **and based on** **ISO/TS 22163:2017**

for the activities of Design and Development and Manufacturing and Maintenance for the scopes of certification: 01 (Vehicle body), 03 (Guidance), 04 (Power system, drive unit), 05 (Auxiliary systems), 06 (Braking system), 14 (Heating, Ventilating and Air Conditioning (HVAC)), 16 (Vehicle linkage devices), 17 (Rolling stock), 19 (Single railway components)

The design, development, production of trains. Rolling Stock Maintenance (coaches and passenger cars and locomotives) Manufacturing of Car Body shell Maintenance of internal combustion machines and traction motors Maintenance of wheelsets elements. Electronic cards repairing.

Certificate valid from: 28/01/2022

Certificate valid until: 08/07/2024*

Current date: 06/04/2022

Certificate-Register-No: IR-2010/004

* Providing that the subsequent surveillance audits are successful before the validity date of the previous audit.
Certification body address: C/ Génova, 6, 28004 Madrid, Spain



Certification

Enclosure 1 of Certificate No.: IR-2010/004

PATENTES TALGO S.L.U.
PASEO DEL TREN TALGO Nº 2
28290, LAS MATAS
Spain

The location is supported by the following site extensions:

Address	Scope/Process
Talgo Maintenance Site San Andres Condal C/ Ferran Junoy S/N 08030, San Andrés Condal, Barcelona,Spain	Maintenance of locomotives, coaches and passenger cars. Maintenance of Air Conditioning equipments, wheelsets elements, of brake components and battery devices
Talgo Maintenance Site Can Tunis C/ Motores S/N 08040, Barcelona,Spain	Maintenance of high speed trains
Talgo Maintenance Site Fuencarral C/ Antonio de Cabezón S/N Fuencarral 28034, Madrid,Spain	Maintenance of high speed trains
Talgo Maintenance Site Las Matas 1 CR. N-VI, km 23.500, 28290, Las Matas. Madrid,Spain	Rolling stock Maintenance Maintenance of air conditioning equipment, wheelsets elements, brake components, coupling devices (automatics and manuals)
Talgo Maintenance Site Santa Catalina Avenida de Santa Catalina, 4. 28053, Madrid,Spain	Maintenance of high speed trains
Talgo Maintenance Site Málaga Camino de los prados, CL Ucrania. 29006 Málaga,Spain	Maintenance of high speed trains
Talgo Rivabellosa C/ Rio Bayas, 5 01213 Rivabellosa,Spain	Production of trains Manufacturing of carbody shells and bogie frames

Current date: 06/04/2022
Certificate-Register-No: IR-2010/004

* Providing that the subsequent surveillance audits are successful before the validity date of the previous audit.
Certification body address: C/ Génova, 6, 28004 Madrid, Spain



Enclosure 2 of Certificate No.: IR-2010/004

PATENTES TALGO S.L.U.
PASEO DEL TREN TALGO Nº 2
28290, LAS MATAS
Spain

The location is supported by the following remote locations:

Address	Scope/Process
Talgo Majadahonda C/ Las Norias, 92 28221 Majadahonda, Madrid, Spain	Supply Chain, Purchasing, Maintenance engineering, Knowledge management



Current date: 06/04/2022
Certificate-Register-No: IR-2010/004



Providing that the subsequent surveillance audits are successful before the validity date of the previous audit.
Certification body address: C/ Génova, 6, 28004 Madrid, Spain