



# C E R T I F I C A T E

awarded to

**PATENTES TALGO S.L.U.**  
**PASEO DEL TREN TALGO Nº 2**  
**28290, LAS MATAS**  
**Spain**

**AENOR INTERNACIONAL, S.A.U.**

confirms, as an IRIS Certification® approved certification body, that the Management System of the above organization has been assessed and found to be in accordance with the

**IRIS Certification® Conformity assessment:2020**  
**and based on**  
**ISO/TS 22163:2017**

for the activities of Design and Development and Maintenance and Manufacturing for the scopes of certification: 01 (Vehicle body), 04 (Power system, drive unit), 14 (Heating, Ventilating and Air Conditioning (HVAC)), 17 (Rolling stock)

The design, development, production of trains. Rolling Stock Maintenance (coaches and passenger cars and locomotives) Manufacturing of Car Body shell Maintenance of internal combustion machines and traction motors

Certificate valid from: 09/07/2021

Certificate valid until: 08/07/2024\*

A handwritten signature in blue ink, appearing to be "J. L. S.", written over a horizontal line.

Current date: 12/03/2021

Certificate-Register-No: IR-2010/004

\* Providing that the subsequent surveillance audits are successful before the validity date of the previous audit.  
Certification body address: C/ Génova, 6, 28004 Madrid, Spain

©2021 UNIFE. All rights reserved.

1/3

Enclosure 1 of Certificate No.: IR-2010/004

**PATENTES TALGO S.L.U.**  
**PASEO DEL TREN TALGO Nº 2**  
**28290, LAS MATAS**  
**Spain**

**The location is supported by the following site extensions:**

Address	Scope/Process
Talgo Maintenance Site San Andres Condal C/ Ferran Junoy S/N 08030, San Andrés Condal, Barcelona,Spain	Maintenance of locomotives, coaches and passenger cars
Talgo Maintenance Site Can Tunis C/ Motores S/N 08040, Barcelona,Spain	Maintenance of high speed trains
Talgo Maintenance Site Fuencarral C/ Antonio de Cabezón S/N Fuencarral 28034, Madrid,Spain	Maintenance of high speed trains
Talgo Maintenance Site Las Matas 1 CR. N-VI, km 23.500, 28290, Las Matas. Madrid,Spain	Rolling stock maintenance. Maintenance of air conditioning equipment
Talgo Maintenance Site Santa Catalina Avenida de Santa Catalina, 4. 28053, Madrid,Spain	Maintenance of high speed trains
Talgo Maintenance Site Málaga Camino de los Prados, CL Ucrania. 29006 Málaga,Spain	Maintenance of high speed trains



Current date: 12/03/2021  
Certificate-Register-No: IR-2010/004

\* Providing that the subsequent surveillance audits are successful before the validity date of the previous audit.  
Certification body address: C/ Génova, 6, 28004 Madrid, Spain



Enclosure 2 of Certificate No.: IR-2010/004

**PATENTES TALGO S.L.U.**  
**PASEO DEL TREN TALGO Nº 2**  
**28290, LAS MATAS**  
**Spain**

**The location is supported by the following remote locations:**

Address	Scope/Process
Talgo Majadahonda C/ Las Norias, 92 28221 Majadahonda, Madrid, Spain	Human Resources, Commercial, Purchasing, Maintenance engineering, Knowledge management

A handwritten signature in blue ink, consisting of several fluid, connected strokes, positioned above a solid horizontal line.

Current date: 12/03/2021

Certificate-Register-No: IR-2010/004

\* Providing that the subsequent surveillance audits are successful before the validity date of the previous audit.  
Certification body address: C/ Génova, 6, 28004 Madrid, Spain

©2021 UNIFE. All rights reserved.